

CENTURY MINE MITIGATION STREAM MITIGATION PHOTOGRAPHS
Long Run



Photograph: 68
LRL-7: Successful log vane and J-hook



Photograph: 69
LRL-7: Unsuccessful coir log and live staking



Photograph: 70
LRL-7: Unsuccessful stream bank restoration



Photograph: 71
LRL-8: Successful steep bank restoration



Photograph: 72
LRL-8: successful log vane and J-hook



Photograph: 73
LRL-10: Successful boulder and toe protection